

2 of 2



Estb. No.: 13-51-07862

STATE OF FLORIDA  
DEPARTMENT OF HEALTH

ESTABLISHMENT NAME: Kenwood K-8 Center  
9300 SW 79 AVE, MIAMI, 33156

COMMENTS AND INSTRUCTION:

- 5-Clean the laundry room inside the boy's locker room.
- 5-6-Replace missing plastic cover (protector) of the light fixture inside bathroom 129-D (girl's lockers).
- 5-Replace water damaged and/or missing ceiling tiles in classroom 128 and the hallway by room 127 (4th floor - annex building).
- 5-Repair damaged baseboard near the door of room 128.
- 11-12. Repair or replace damaged floor around the toilet in the pre-k room
- 5-Eliminate several cables hanging behind two rows of computers in the pathway of the students (tripping and/or equipment pulling hazard). This can be solved by placing the 2 rows of computer desks back to back and not leaving a passage way between them. This is in classroom 012.
- 11-Clean the urinals of the boy's bathroom in the old building.
- 11-12. Repair or replace slow flushing toilet in the men's bathroom by the cafeteria
- 11-Clean handwash sinks, urinals, floors, vents and walls of bathrooms 908, 908
- 5-Clean dust on several surfaces of the 900 building (except rooms 913, 914, 915 and 916), the annex building (2nd floor is worse), the pre-k portable, the media center, and classrooms 004, 005, 006, 007, 008, 009, 016, 017, 011, 014, 015 and 019.
- 15- Provide a soap dispenser for the handwash sink of classroom 017.
- 5-Clean the sinks and walls near the sinks of room 121 (art lab.).
- 5-Clean the floors of the 900 building, the 1st floor of the annex bldg. and classrooms 005 & 016.

Copy of Inspection Report Received by: X Adriana Almeida - R

Health Department Inspector: Oswaldo Saucy

Date: 02/24/2011